





Plantation Desk & Return


Assembly Instructions

Plantation Desk & Return


Components List




2 x Worktop




EL 6 x Meeting Table Legs
75° Angle




B 6 x L & R Pair AXKDSPIGE
& 1 x L AXKDSPIGE




C 1 x Pair L & R AXKDBRAC
& 1 x R AXKDBRAC




D 1 x PLRAILMOUNT



E 2 x Worktop Joining Plate



SB 3 x Straight Spreader Bar
to suit Straight Legs



R 2 x Extendable Desk Rail



16 - M6 x 20



26 - M8 x 16



24 - ST8 x 23



9 - ST6 x 23



2 - ST5 x 23




16 - ST8 x 20

STEP 1:





12 - M6 x 20





Plantation Desk & Return

Assembly Instructions

STEP 2:





STEP 3:



Plantation Desk & Return

Assembly Instructions

STEP 4:




STEP 5:



4 - M8 x 16





4 - M6 x 20



Plantation Desk & Return

Assembly Instructions

STEP 6:




STEP 7:



24 - ST8 x 23




9 - ST6 x 23



2 - ST5 x 23




16 - ST8 x 20



Plantation Desk & Return


Assembly Instructions

Complete:



Optional E-Panel Modesty


Assembly Instructions




Optional E-Panel Modesty

Assembly Instructions

STEP 1:



STEP 2:



Optional E-Panel Modesty

Assembly Instructions

Complete:

